



DEFECTS OF STEEL BILLETS AND METAL PRODUCTS

HANDBOOK-ATLAS

*Under the general editorship of Anatoly Nikolaevich Savenok,
Director General of OJSC "Byelorussian Steel Works – management company
of "Byelorussian Metallurgical Company" holding"*





TABLE OF CONTENTS

NORMATIVE REFERENCES.....	14
INTRODUCTION	16
CHAPTER 1. STEEL QUALITY AND CLASSIFICATION OF DEFECTS	18
1.1. Classification of defects	18
1.2. Comprehensive strategy for quality of metallurgical products.....	21
CHAPTER 2. STEELMAKING	25
2.1. Melting, extra-furnace steel processing.....	26
2.2. Continuous steel casting	26
2.3. Processes of concast billet defect formation	29
CHAPTER 3. DEFECTS OF CONCAST BILLET	32
125×125 mm, 140×140 mm, 250×300 mm, 300×400 mm in section, Ø200 mm.....	32
3.1. Shape defects.....	32
3.1.1. Swelling (crown)	32
3.1.2. Concavity	33
3.1.3. Ovality	33
3.1.4. Longitudinal shrinkage depressions (scabs)	34
3.1.5. Rhomboidity	35
3.2. Surface defects.....	36
3.2.1. Non-metallic inclusions on the surface	36
3.2.2. Skin ripples	37
3.2.3. Longitudinal cracks.....	37
3.2.4. Transverse cracks	38
3.2.5. Reticular cracks	39
3.2.6. Belt.....	40
3.2.7. Mechanical defects (mark)	41
3.2.8. Folds	41
3.2.9. Pores.....	42
3.2.10. Metal bleeding	43
3.3. Internal defects	43
3.3.1. Centerline (axial) porosity.....	43
3.3.2. Segregation streaks and cracks	44
3.3.3. Edge point contamination	46
3.3.4. Ghost line (contour)	47
3.3.5. Centerline segregation	47
3.3.6. Irregular transgranular structure	49



3.3.7. Pinhead blisters	49
3.3.8. Foreign metallic inclusions	50
3.3.9. Non-metallic inclusions.....	51
3.4. Classifier of defects of concast billet macrostructure (sulphur prints prepared by Baumann's method)	52
3.4.1. Centerline (axial) porosity.....	52
3.4.2. Centerline segregation (axial chemical inhomogeneity)	53
3.4.3 Segregation streaks and cracks (common, corner, axial).....	55
3.4.4. Edge point contamination.....	60
3.4.5. Ghost line (contour).....	61
3.4.6. Pinhead blisters.....	62
CHAPTER 4. ROLLED SECTION STEEL PRODUCTION	63
4.1. Process operations and characteristics of rolling mill 850	63
4.2. Process operations and characteristics of small-section rolling mill 320	65
4.3. Process operations and characteristics of rod mill 150.....	66
4.4. Processes of formation of rolled section steel defects.....	68
4.4.1. Billet defects	68
4.4.2. Defects of section steel and wire rod	69
CHAPTER 5. ROLLED SECTION STEEL DEFECTS	71
5.1. Shape defects	71
5.1.1. Ridge	71
5.1.2. Abnormal sectional shape (oval).....	72
5.1.3. Apex angle underfilling.....	72
5.1.4. Flat regions of the surface.....	73
5.1.5 Die-rolled section underfilling	74
5.2. Surface defects	75
5.2.1. Rolled crack.....	75
5.2.2. Reticular rolled crack.....	77
5.2.3. Rolled blister.....	79
5.2.4. Rolled crust.....	81
5.2.5. Rolled slag patch	82
5.2.6. Small breaks.....	83
5.2.7. Ingot hot tear	84
5.2.8. Deformational tear	85
5.2.9. Guide mark (scratch, score mark) inherited from concast billets	86
5.2.10. Guide mark.....	89
5.2.11. Dent.....	91
5.2.12. Wrinkles.....	91



5.2.13. Rolling lap	92
5.2.14. Rolled scab	92
5.2.15. Fish scale	93
5.2.16. Backfin	94
5.2.17. Roll marks	95
5.2.18. Scale pits	95
5.2.19. Stress crack	96
5.2.20. Rolled-in metal particles	97
5.2.21. Scuff marks	98
5.2.22. Rust spots	99
5.2.23. Rolled-in scale	99
5.2.24. Surface scale of non-conforming weight or composition	100
5.3. Internal defects	101
5.3.1. Flakes	101
5.3.2. Structure inhomogeneity	102
5.3.3. Cast structure residue	103
5.3.4. Segregation streaks	104
5.3.5. Foreign metallic inclusions	105
5.3.6. Centerline segregation	105
5.3.7. Grinding cracks	106
5.3.8. Delamination	107
5.3.9. Non-metallic inclusions	107
5.3.10. Pipe segregation	109
5.4. Structural defects of high-carbon wire rod (mill 150)	110
5.4.1. Structure of different graininess	110
5.4.2. Secondary sorbite in a surface layer	111
5.4.3. Troostite-martensite areas	112
5.4.4. Higher content of ferrite	112
5.4.5. Coarse pearlite	113
5.4.6. Cement carbide precipitation at the grain boundaries	113
5.4.7. Banding (secondary segregation)	114
5.4.8. Surface decarburization	115
CHAPTER 6. HOT-ROLLED PIPE MAKING	116
6.1. Basic operations of hot-rolled pipe making	116
6.2. Main product mix of pipe rolling plant	118
6.3. Process description of hot-rolled pipe making	119
6.3.1. Billet heating and pipe piercing	119
6.3.2. Pipe rolling on continuous rolling mill, stretch-reducing mill and extractor	119



6.3.3. Pipe prefinishing	120
6.3.4. Pipe finishing and heat treatment.....	121
6.4. Defect formation processes in the pipe making area	121
CHAPTER 7. DEFECTS OF HOT-ROLLED STEEL PIPES.....	123
7.1. Shape defects	123
7.1.1. Ridge	123
7.1.2. Scab	124
7.1.3. Cobble	126
7.1.4. Polygonization	127
7.1.5. Variation in wall thickness	127
7.1.6. Unfinished section	128
7.2. Pipe surface defects inherited from concast billet.....	129
7.2.1. Steel-smelting slivers on blowholes and rolled blisters.....	129
7.2.2. Steel-smelting slivers on hot and hot rolled cracks	131
7.2.3. Steel-smelting slivers and bubbles on endogenous non-metallic inclusions	132
7.2.4. Steel-smelting slivers and bubbles on exogenous non-metallic inclusions	133
7.2.5. Steel-smelting slivers and delaminations on the rolled crust	134
7.2.6. Steel-smelting slivers and delaminations on axial burning	136
7.2.7. Steel-smelting slivers on segregation streaks and cracks	137
7.3. Pipe surface defects of rolling origin	138
7.3.1. Pipe-rolling lap.....	138
7.3.2. Undercutting	139
7.3.3. Guide mark.....	141
7.3.4. Wrinkles.....	141
7.3.5. Roll marks.....	142
7.3.6. Mechanical damage	143
7.3.7. Dent mark.....	144
7.3.8. Pigeon hole.....	145
7.3.9. Fish scale	146
7.3.10. Backfin.....	147
7.3.11. Tear	148
7.3.12. Ragging marks	148
7.3.13. Roll marks (from rolled-in scale).....	149
7.3.14. Foreign metallic inclusions	151
7.4. Defects of pipe-rolling origin on the inner pipe surface.....	151
7.4.1. Pipe-rolling slivers and bubbles.....	151
7.4.2. Ripple markings	152
7.4.3. Wrinkles.....	153



7.4.4. Backfin	154
7.4.5. Foreign metallic inclusions	155
7.4.6. Pipe-rolling crack	156
7.4.7. Guide scratch.....	157
7.4.8. Guide mark	159
7.4.9. Dent mark	159
7.5 Surface finish defects	160
7.5.1. Scratch.....	160
7.5.2. Fin.....	161
7.5.3. Indentation	162
7.6. Heat treatment defects	163
7.6.1 Thermal crack	163
CHAPTER 8. HARWARE PRODUCTION.....	165
8.1. Production of steel cord, brass-plated hose wire and bronze-plated bead wire	167
8.2. Production of wire of different purpose and cold-deformed reinforcement in coils using mechanical method of scale removal	171
8.2.1. Manufacturing process of wire of different purpose	171
8.2.2. Manufacturing process of cold-worked deformed reinforcing steel bars	172
8.2.3. Manufacturing process of steel wire fibers	172
8.3. Main groups of defects of hardware production	173
8.3.1. Defects of steel cord, brass-plated hose wire and bronze-plated bead wire.....	173
8.3.2. Defects of cold-drawn deformed reinforcing steel bars	174
8.3.3. Defects of steel wire fibre	175
8.4. Inspection of defects of hardware production.....	175
CHAPTER 9. DEFECTS OF HARDWARE ITEMS	179
9.1 Defects of wire rod transportation, storage and preparation to drawing	179
9.1.1. Defects of wire rod transportation and storage	179
9.1.1.1. Surface contamination of wire rod bundle	179
9.1.1.2. Corrosion stains.....	179
9.1.1.3. Mechanical damages.....	180
9.1.2. Defects occurring at the stage of preparation of the wire rod surface to drawing	181
9.1.2.1. Underpickling	181
9.1.2.2. Presence of powdered sodium borate.....	182
9.2. Defects of cold-drawn wire	183
9.2.1. Surface defects inherited from wire rod.....	183
9.2.1.1. Surface defect in the area of rolled blister	183
9.2.1.2. Surface defect on rolled contamination	184
9.2.1.3. Rolled-in metal particles	185



9.2.1.4. Surface defect due to foreign metallic macroinclusions	186
9.2.1.5. Backfin on the wire surface	187
9.2.1.6. Surface defect due to chemical inhomogeneity	188
9.2.1.7. Surface defect due to mechanical damages of wire rod	189
9.2.2. Internal defects inherited from wire rod	191
9.2.2.1. Exogenous non-metallic inclusions	191
9.2.2.2. Axial chemical inhomogeneity (segregation).....	191
9.2.2.3. Coarser-grained perlite.....	192
9.2.3. Surface defects of wire occurring during drawing	193
9.2.3.1. Guide mark.....	193
9.2.3.2. Scuff marks (abrasions)	194
9.2.3.3. Glossy surface.....	195
9.2.3.4. Surface defects formed during wire drawing.....	195
9.2.3.5. Surface stress cracks	196
9.2.3.6. Surface defects in welding points.....	197
9.2.3.7. Breakage due to increased tension stresses (contraction)	198
9.3. Defects of patented and brass-plated wire bar	199
9.3.1. Surface defects	199
9.3.1.1. Surface defects on brass-plated wire inherited from wire rod.....	199
9.3.1.2. Surface defects of drawing.....	200
9.3.1.3. Guide marks	201
9.3.1.4. Pits.....	202
9.3.1.5. Burn from sparks	202
9.3.1.6. Mechanical damage of brass coating.....	203
9.3.2. Coating defects	204
9.3.2.1. Peeling of brass coating	204
9.3.2.2. Dark strips and spots.....	205
9.3.2.3. Zinc strip	206
9.3.2.4. Lead sticking.....	207
9.3.2.5. Sticking of aluminium oxide particles (sand)	208
9.3.2.6. Brass sticking	209
9.3.2.7. Carbon black contamination of the surface	210
9.3.3. Defects of patented wire bar microstructure	210
9.3.3.1. Inconsistent perlite structure	210
9.3.3.2. Presence of divorced (globular) cementite.....	211
9.3.3.3. Presence of upper bainite	212
9.3.3.4. Presence of structurally free ferrite	213
9.3.3.5. Surface decarburization	214



9.3.3.6. Surface overheating.....	215
9.3.3.7. Overheating with decarburization (stagnant end).....	215
9.4. Surface defects of fine brass-plated wire	216
9.4.1. Wire defects.....	216
9.4.1.1. Guide marks	216
9.4.1.2. Absence of coating on fine wire (gray wire).....	217
9.4.1.3. Wire surface contamination	217
9.4.1.4. Wire corrosion.....	218
9.5. Steel cord defects.....	219
9.5.1. Non-conformance of geometric parameters of steel cord	219
9.5.1.1. Steel cord diameter and linear density out of tolerance	219
9.5.1.2. Lay length out of specification	220
9.5.1.3. Loose lay	220
9.5.1.4 Uneven coiling	221
9.5.1.5 Air cell	221
9.5.1.6. Macrowave	222
9.5.1.7. Microwave.....	223
9.5.1.8. Breakout of the core (central wire)	224
9.5.1.9. Inversion	224
9.5.1.10. Knot.....	225
9.5.1.11. Crease mark	226
9.5.1.12. Out-of-straightness	227
9.5.1.13. High residual spinning	228
9.5.1.14. Non-spinning degree out of tolerance	228
9.5.1.15. Corrosion	229
9.5.2. Low-quality spooling of steel cord on the bobbin	230
9.6. Breakages during fine wire drawing and steel cord coiling	231
9.6.1. Breakages on the surface defects of wire	231
9.6.1.1. Breakages on the surface defects formed before the stage of brass plating	231
9.6.1.2 Breakages on the surface defects of fine drawing	232
9.6.1.3. Breakage on the hard alloy inclusions.....	233
9.6.1.4. Breakages on the surface inclusions of martensite (sparking).....	233
9.6.2. Breakages due to internal defects of wire	234
9.6.2.1. Non-metallic inclusion.....	234
9.6.2.2. Breakages of axial crack type (cone-dimple).....	235
9.6.3. Wire breakages due to higher external forces.....	238
9.6.3.1. Contraction during wire fracture of steel cord.....	238
9.6.3.2. Breakages of steel cord wires when twisting.....	239



9.6.4. Other breakages.....	239
9.6.4.1. Breakages on the surface defects of coiling	239
9.6.4.2. Breakages due to high strain hardening of wire (delamination).....	240
9.6.4.3. Breakage due to low-quality welding on the fine drawing section.....	241
CHAPTER 10. PRODUCTION OF DRAWING DIE TOOL	242
10.1. Technique of drawing die tool making of hard alloys	242
10.2. Processes of defect formation during production and operation of the drawing die tool of hard alloys	247
CHAPTER 11. DEFECTS OF DRAWING DIE TOOL	249
11.1. Hard-alloy defects after sintering treatment	249
11.1.1. Foreign inclusions	249
11.1.2. Ring pores	250
11.1.3. Visible porosity of type I	251
11.1.4. Single pores.....	252
11.1.5. Visible porosity of type II (structurally-free carbon).....	252
11.1.6. η -phase.....	253
11.1.7 Uneven distribution of β -phase particles	254
This defect can be eliminated by replacement of the low-quality lot of powder mixture and by compliance with the sintering conditions.	255
11.1.8. Variation in grain size of α -phase.....	255
11.1.2. Slip cracks	256
11.1.3 Swell	256
11.2. Defects of hard alloy mechanical processing.....	257
11.2.1. Split of hard alloy insert.....	257
11.2.2. Transverse cracks	258
11.2.3. Inlet cone cleavage	259
11.2.4. Outlet cone cleavage.....	260
11.2.5. Inadequate surface finish	261
11.2.6. Longitudinal cracks.....	261
11.2.7. Corrosion stains	262
11.3. Deviation of physical and mechanical properties of drawing die tools.....	263
11.3.1. Low density.....	263
11.3.2. Discrepancy of coercive force value	264
11.3.3. Low hardness	264
11.4. In-service defects of drawing die tool.....	265
11.4.1. Cracks	265
11.4.2. Longitudinal cracks.....	265
11.4.3. Transverse cracks	265
11.4.4. Breakout of a part of the hard alloy die blank.....	266



11.4.5. Destruction of outlet cone	267
11.4.6. Split of hard alloy insert	267
11.4.7. Full breakout of hard alloy insert	268
11.4.8. Striations	268
11.4.9. Wear ring	269
11.4.10. One-sided working-out	270
11.4.11. Pitting	271
11.4.12. Brass and scale sticking	272
11.4.13. Micropitting	272
11.4.14. Inadequate processing of the die exit.....	273
REFERENCES	274
References to Chapters 1–3.....	274
References to Chapters 4–5.....	276
References to Chapters 6–7	279
References to Chapters 8–9.....	284
References to Chapters 10–11.....	286